APPLICATION INSTRUCTIONS

MoZaic

Printable flex film for easy cutting and weeding!
Can be used without tape.

OEKO-TEX® STANDARD 100
CQ 730/3 IFTH
www.oeko-tex.com

Certified for HP Latex Inks

FEATURES:

PU water-based	**75μ**	**Cotton, polyester, blended fabrics..** Less suitable for nylon and other coated textiles.		**EcoSolvent (incl. TrueVis), Solvent, Latex, UV**

1. Print and cut

CUTTING CONDITIONS:

Blade 30 - 45°	**low/ medium**	**30 - 40 cm/s**

2. Weed design

TRANSFER CONDITIONS 1:

150°C	**5 s**	**medium/ high**	**Hot peel**	**60°C**

3. Apply tape

TRANSFER CONDITIONS 2:

130°C	**10 s**	**medium/ high**	**Hot peel**	**60 °C**

4. Transfer, remove tape, done !

Printing profiles at www.seftextile.com

Recommended transfer tape: FlexTape; connected designs can also be transferred without tape.

Drying time: Depending on ink and conditions 1 - 6h

For small designs, it can be usefull to first apply the tape over the whole surface and then to weed it from the back.

▶ **PACKAGING**

50 cm	25 m
75 cm	25 m